Manhole Inspection Summary N				anhole	ИH	
Printed On: 6/24	/2010			Page 1 c	of 4	
Inspection	☐ Is Incomplete	Rating: 3) Fair				
Record Plat: 47	'MM Node: 031	Status: Found		Insp Date: 5/7/08 1:05 P	М	
Incomplete Cor	nments			Crew: ct,jf Inspector: Provine, D Firm: JV		
Location	Address: Collington Ave			Cross Street: Sinclair Ln		
Manhole	Type: Junction	Location: Roadway		Ground Conditions: Dry		
		Weather: Dry		Subject To Ponding: None		
Comments	Complete					
Cover	Shape: Circular	Diameter: 30	(in.) Lengt	th: (in.) Dist A/B Grade: 0	(in.)	
	Type: Sanitary	Condition: Sou	nd	Cover Material: Cast Iron		
Properties: Bolted Vented Water Tight Water Tight Insert						
Frame Offset: 2 (in.) Condition: Sound Cracked Leaks						
Chimney / Frame Adjustment						
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ✓ Loose Brick ☐ Deteriorated						
Infiltration: None / Joint Cracks / Mortar Roots Wall						
Corbel	Material: Brick	☐ Parg	ed Type:	Concentric/Eccentric		
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated					
Infiltration:	☐ None ☐ Joint	☐ Cracks ☐ Mor	tar 🗌 Ro	ots V Wall		
Barrel	Material: Brick	☐ Parg	ed			
Shape:	Circular Dia	ameter: 42 (in.) Len	gth: (in.)			
Condition:	✓ Sound ☐ Cracke	ed Root Intrusion	Loose	Brick Deteriorated		
Infiltration:	☐ None ☐ Joint	☐ Cracks ☐ Mor	tar 🗌 Ro	ots 🗸 Wall		
Bench	✓ Exists Material: E	Brick	☐ Parge	d		
Condition:	✓ Sound ☐ Cracke	ed Root Intrusion	☐ Deteri	orated Leaks Debris		
Channel	Material: Brick	☐ Parg	ed			
Channel E	xposure: Fully Open	Junc Dist: 0	nearest .	5 ft. Azimuth:		
Condition:	✓ Sound ☐ Cracke	ed Root Intrusion	☐ Deteri	orated Leaks Debris		
Steps	Count: 6 Missing:	2 Corroded				
Surcharge	Evidence Of Surc	harge Depth:	(ft.)	ve Surcharge Present		

Manhole Inspection Summary

Manhole # S47MM_031MH

Printed On: 6/24/2010 Page 2 of 4

Location View



Defect 2



missing steps

Top View



Defect 1



infiltration, Loose bricks

Manhole Inspection Summary

Manhole # S47MM_031MH

Printed On: 6/24/2010 Page 3 of 4

12 in. Circular Gravity Sewer Pipe Out @ 12 O'Clock





Pipe Height: 12 (in.) Rod and Bar (Angled)

Pipe Material: Clay

Invert Depth: 12.55 (ft.) Flow Characteristics: Fast

Deposits: \subseteq None \subseteq Mud \subseteq Sludge \subseteq Debris \subseteq Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: None Pipe Seal Cond: Sound

Drop: None

Connects To: Manhole

☐ Possible Illicit Connection

10 in. Circular Gravity Sewer Pipe In @ 6 O'Clock





Pipe Height: 10.8 (in.) Rod and Bar (Angled)

Pipe Material: Clay

Invert Depth: 12.20 (ft.) Flow Characteristics: Fast

Silt Depth: (in.) Deposits Extent:

Infiltration: None Pipe Seal Cond: Sound

Drop: None

Connects To: Manhole

☐ Possible Illicit Connection

Manhole Inspection Summary

Manhole # S47MM_031MH

Printed On: 6/24/2010 Page 4 of 4

10 in. Circular Gravity Sewer





Drop: None
Connects To: Manhole
Possible Illicit Connection